



Broj šasije: W1K4F1CB1PJ439575

Gorivo: Dizel

Godina: 2022

Vrsta mjenjača: Automatski



Kilometraža

✔ Nisu pronađeni problemi

Posljednja zabilježena kilometraža:
91.917 km.

Provjera pravnog statusa

✔ Nisu pronađeni problemi

Nisu pronađeni zapisi o financijskim ili pravnim rizicima.

Oštećenje

✔ Nisu pronađeni problemi

Nisu pronađeni zapisi o oštećenjima ili procjeni.

Krađa

✔ Nisu pronađeni problemi

Nema podataka o krađi.

Emisije

✔ Nisu pronađeni problemi

Niska razina CO₂ emisija: 133 g/km.

Izloženost prirodnim katastrofama

✔ Nisu pronađeni problemi

Nisu pronađeni zapisi o izloženosti prirodnim katastrofama.



+36

Izvori podataka

Provjerili smo 900+ izvora podataka u 40 država

Krađa

Provjerili smo je li vozilo trenutno navedeno kao ukradeno, je li ikada u prošlosti prijavljeno kao ukradeno i je li pronađeno.



Dobre vijesti

Nismo pronašli nikakve podatke da je vozilo ukradeno.



Sažetak

Provjera baze podataka ukradenih vozila izvršena je u 7 država: +1

Evo što smo provjerili:



Traži li se trenutno kao ukradeno?

✔ Podaci nisu pronađeni



Je li vozilo bilo ukradeno u prošlosti?

✔ Podaci nisu pronađeni

Za ovo vozilo nisu pronađeni zapisi o krađama u prošlosti.

Provjera policijske baze podataka ukradenih vozila izvršena je u sljedećim državama:

Slovačka Češka Slovenija Rumunjska Mađarska Italija Kanada


Kilometraža

Provjerili smo je li kilometraža točna ili je možda bila lažirana.



Sažetak

- Posljednja poznata kilometraža: 91.917 km
- Prosječna kilometraža sličnih modela: 50.930 km
- Pronađeno je 5 zapisa o kilometraži



Zapisi brojača kilometara

| | |
|-----------|-----------|
| 09. 2022. | 11 km |
| 06. 2023. | 27.875 km |
| 12. 2023. | 54.688 km |
| 12. 2024. | 74.381 km |
| 11. 2025. | 91.917 km |

Vozačke navike

| | | |
|-----------------------|-------------------|-------------------|
| 09. 2022. - 12. 2023. | Intenzivna vožnja | 3.797 km/mjesečno |
| 12. 2023. - 11. 2025. | Uobičajena vožnja | 1.593 km/mjesečno |

Provjera pravnog statusa

Provjerili smo je li vozilo prošlo tehničke preglede i je li označeno kao otpad.

✓ **Dobre vijesti**
Nisu pronađeni podaci o pravnom statusu ovog vozila

Pravni status

- ✓= Je li vozilo prošlo tehnički pregled? ✓ Podaci nisu pronađeni Nisu pronađeni podaci o tehničkom pregledu
- ↺↻ Je li bilo označeno kao otpad? ✓ Podaci nisu pronađeni Nema podataka da je vozilo označeno kao otpad

Oštećenje

Je li ovo vozilo bilo oštećeno u prošlosti? Kolika je bila vrijednost štete?

✓ **Dobre vijesti**
Nisu pronađeni zapisi o oštećenjima ili procjeni



Ponekad mogu biti prikazane netočne informacije, posebno u slučaju provjere starijih vozila. Neovlašteni servisi mogu ilegalno zamaskirati nedostatke ili oštećenja na vozilu, a da pritom nisu nigdje zabilježena. Ponekad može biti zamijenjena čak i pločica s brojem šasije vozila. Koristimo različite metode da bismo otkrili takve prekršaje, ali nemoguće je dati 100 %-tnu garanciju.

Izloženost prirodnim katastrofama

Provjerili smo je li se vozilo nalazilo u području pogođenom prirodnim katastrofama u trenutku kada su se dogodile.



Dobre vijesti

Lokacija ovog vozila nije zabilježena na području prirodnih katastrofa.

Tržišna cijena


Provjerili smo kako se tržišna cijena ovog vozila mijenjala tijekom vremena, na temelju dostupnih povijesnih podataka i procjena cijena.

Vremenska crta prikazuje ograničeno razdoblje i ne odražava cijenu vozila tijekom cijelog njegovog životnog vijeka.



Sažetak

- Prosječna tržišna cijena za ovakvo vozilo: 26.368 €
- Budi na oprezu zbog mogućih skrivenih problema ako se vozilo prodavalo po znatno nižoj cijeni od trenutne!



| Year | Tržišna cijena | ↘ Najniža tržišna vrijednost | ↗ Najviša tržišna vrijednost |
|--------|----------------|------------------------------|------------------------------|
| ● 2024 | 31.900 € | 27.454 € | 36.500 € |
| ● 2025 | 27.490 € | 22.690 € | 33.009 € |
| ● 2026 | 26.368 € | 22.000 € | 32.066 € |
| ● 2027 | 25.900 € | 21.610 € | 31.497 € |
| ● 2028 | 23.499 € | 19.606 € | 28.577 € |
| ● 2029 | 21.900 € | 18.272 € | 26.632 € |
| ● 2030 | 16.900 € | 14.100 € | 20.552 € |
| ● 2031 | 15.990 € | 13.341 € | 19.445 € |
| ● 2032 | 13.999 € | 11.680 € | 17.024 € |
| ● 2033 | 13.440 € | 11.214 € | 16.344 € |

Uvidi u tržišne cijene



Prognoza trenda cijena

Očekuje se da će ovo vozilo izgubiti -49% svoje tržišne cijene u sljedećih 7 godina.



Pad cijena i razdoblje za povoljnu kupnju

Najveći pad tržišne cijene očekuje se oko 2030. godine, kada vozilo bude staro 8 godina. Kupnja tijekom ovog razdoblja mogla bi biti najpovoljnija



Optimalno vrijeme za prodaju

Prodaja vozila prije najvećeg pada cijene – koji se očekuje oko 2029. godine ili kada vozilo bude staro 7 godina – može ti pomoći da zadržiš veći dio vrijednosti.

Napomena: Predviđanja se temelje na trenutnim trendovima na tržištu i povijesnim podacima. Stvarna vrijednost pri preprodaji može se promijeniti zbog promjena na tržištu, stanja, lokacije ili drugih čimbenika.

Emisije

Analizirali smo koliko CO₂ ovaj model automobila obično proizvodi i koji se porezi ili naknade mogu primjenjivati.



carVertical uvid

Ovo vozilo ima prosječne emisije. To će vjerojatno uključivati standardne poreze na emisije.

Emisije CO₂

Emisija CO₂ g/km

Emisija CO₂ tvog vozila **133 g/km** Razred **B**

Do 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 +

Specifikacije & oprema

Tehničke specifikacije vozila i originalna oprema u zapisu.

Ovaj odjeljak sadrži pojednostavljene opise generirane uz pomoć umjetne inteligencije koji će ti pomoći da bolje razumiješ svaku značajku vozila.



Sažetak

Provjeri odgovaraju li specifikacije i oprema vozila onome što ti je rekao prodavač.

Identifikacija i tehničke specifikacije



Proizvođač

Mercedes-Benz



Varijanta

d



Godina modela

2023



Vrsta goriva

Dizel



Broj vrata

5



Model

B 200



Vrsta karoserije

Višenamjensko vozilo



Zapremnina pogonskog sklopa

2 l



Vrsta prijenosa

Automatski



Položaj volana

**Volan na lijevoj strani
upravljačke konzole**



Opis

B 200



Godina proizvodnje

2022



Snaga pogonskog sklopa

110 kW (148 hp / 150 PS)



Vrsta pogona

Pogon na prednje kotače (FWD)



Broj cilindara

4

Oprema

Kako je primljeno od proizvođača

00U SERVICES FOR REMOTE ACCESS

Includes services for remote access

0B2 VEHICLE PRODUCTION LOCATION RASTATT

Vehicle produced in Rastatt

132 CHANGEOVER OF AIRBAG CU, SOFTWARE AND CRASH SENSOR

Implements changes to airbag control unit, software, and crash sensor for improved performance and safety

14U SMARTPHONE INTEGRATION PACKAGE

Package for smartphone integration included

16U APPLE CARPLAY SMARTPHONE INTEGRATION

Supports Apple CarPlay smartphone i

1B3 COMMUNICATION MODULE ECE VERSION

ECE version communication

218 REAR VIEW CAMERA

Includes rear view camera for addc

235 ACTIVE PARKING ASSIST

Active parking assist s

07B OPERATING INSTRUCTIONS AND SERVICE BOOKLET-FRENCH

Operating instructions and service booklet in French

0S3 COUNTRY COLLECTOR FOR RED CERTIFICATION FOR HU ECE

Country collector for red certification for Hungary ECE

144U DIGITAL WHITE - METALLIC FINISH

Paint color: Digital White with metallic finish

163 TECHNICAL BODY-IN-WHITE OPTIMIZATIONS 2021/2022

Technical body-in-white optimizations for 2021/2022

17U ANDROID AUTO SMARTPHONE INTEGRATION

Supports Android Auto smartphone i

20U KEYLESS RENTAL

Keyless rental fea

234 BLIND SPOT MONITORING

Blind spot monitc

243 ACTIVE LANE KEEPING ASSIST (CAMERA)

Active lane keeping assist with camera t

249 AUTOMATIC DIMMING INSIDE REARVIEW MIRROR AND OUTSIDE MIRRORS

✦ Automatic dimming rearview mirror and s

258 COLLISION WARNING SYSTEM WITH FCW-STOP ACTIVE BRAKE APPLICATION

✦ Collision warning system with active brake

273 EXIT WARNING ASSISTANT

✦ Alerts the driver about nearby obstacles w

287 THROUGH-LOADING FEATURE

✦ Through-loading feature in

2U1 RADIATOR SHUTTER

✦ Includes a radiator s

310 DOUBLE CUP HOLDER

✦ Double cup holder included for co

311A FABRIC - BLACK / ANTHRACITE

✦ Black/anthracite f

345 RAIN SENSOR

✦ Rain sensor techn

355 PREINSTALLATION FOR RETROFITTING NAVIGATION SYSTEM

✦ Preinstallation for retrofitting navigation syst

365 HARD DRIVE NAVIGATION

✦ Equipped with a hard drive navigati

3U6 HU COUNTRY SET FOR ECE/ROW

✦ HU country set for ECI

428 STEERING WHEEL GEARSHIFT BUTTONS/STEERING WHEEL

GEARSHIFT PADDLES - PAINTED

✦ Steering wheel with gearshift buttons/pad

446 TOUCHPAD ONLY

✦ Touchpad control system in

475 TIRE PRESSURE MONITOR (TPM)

✦ Tire pressure monitoring

500 ELECTRICALLY FOLDING EXTERIOR MIRRORS

✦ Exterior mirrors that electric

504 SPEED SIGN RECOGNITION

✦ Supports speed sign recognition for enh

255B MB-MOBILO WITH DSB AND GGD

✦ Mobile service with repair and breakdown

270 GPS AERIAL

✦ GPS antenna incl

286 LUGGAGE NETS TO LEFT AND RIGHT DRIVER SEAT BACKRESTS

✦ Luggage nets located behind the d

294 KNEEBAG

✦ Kneebag protection inc

2U8 ALTERNATIVE REFRIGERANT

✦ Uses alternative refrig

310A FABRIC

✦ Fabric se:

337B INSTRUMENT CLUSTER/HU LANGUAGE - FRENCH

✦ Instrument cluster and head unit languag

351 ECALL EMERGENCY CALL SYSTEM

✦ E-Call emergency call system ir

362 HERMES COMMUNICATIONS MODULE LTE

✦ Hermes communications module with LTE

367 PRE-INSTALLATION FOR LIVE TRAFFIC INFORMATION

✦ Preparation for receiving live traffic i

426 AUTOMATIC DUAL-CLUTCH TRANSMISSION, 8-SPEED

✦ Includes automatic dual-clutch transmission v

440 CRUISE CONTROL

✦ Cruise control functionality a

458 INSTRUMENT CLUSTER DISPLAY S

✦ Instrument cluster display with

485 COMFORT SUSPENSION

✦ Comfort suspension in

502 MULTI-YEAR FREE MAP UPDATES

✦ Free map updates for multip

51B RATING, COUNTRY GROUP EURO-NCAP

✦ Euro-NCAP country grou

51U HEADLINER, BLACK FABRIC

- Black fabric headliner

537 DIGITAL RADIO STANDARD DAB (DIGI. AUDIO BROADC.)

- Standard digital radio with DAB tuner

548 CONNECT 20 MID (NTG6)

- Connect 20 multimedia system

5S9 REINFORCED SLIDING SLEEVE (8-SPEED DCT)

- Upgraded sliding sleeve for smoother shifting with 8-speed transmission

632 HEADLAMPS, LED, STATIC, RIGHT-SIDE TRAFFIC

- LED headlamps with static function for right-side traffic

6S8 CONTROL CODE - HERMES 2.1B - COUNTRY COLLECTOR

- Control code for Hermes 2.1B country collector

79B PRE-INSTALLATION FOR DIGITAL RADIO STANDARD DAB/DMB

- Preparation for digital radio standard DAB/DMB

7U2 SEAT MODEL VARIANT 2

- Variant 2 of seat model

840 GLAS DUNKEL GETÖNT

- Dark tinted glass

873 SEAT HEATERS FOR DRIVER AND FRONT PASSENGER

- Heated seats for driver and front passenger

889 KEYLESS-GO

- Keyless-go system for entry

8U6 ASSISTANCE SYSTEM STEERING WHEEL CONTROL CHANGEOVER

- Assistance system control switch on steering wheel

927 EXHAUST TREATMENT, EURO 6 TECHNOLOGY

- Exhaust system compliant with Euro 6 technology

968 EURO 6 TECHNOLOGY COC DOCUMENT - WITHOUT MOTOR VEHICLE REGISTRATION CERTIFICATE, PART 2

- Euro 6 technology COC document without vehicle registration certificate

986 DIFFERENT VIN WITH MODEL YEAR

- Vehicle identification number is unique to model year

998 CONTROL CODE FOR CONVERSION TO WLTP WITH RDE

- Control code for conversion to WLTP with RDE

B51 TIREFIT

- Equipped with Tirefit

531L FRANCE

- Vehicle configured for France

543 SUN VISOR WITH ADDITIONAL FUNCTION

- Sun visor with additional function

580 AIR-CONDITIONING SYSTEM

- Air-conditioning system equipped

5XXL EUROPE

- Euro-spec vehicle

6P5 CONTROL CODE FOR SALES

- Control code used for sales purposes

73B ROLLER BLIND COMPARTMENT CLOSED

- Roller blind compartment closed

7B4 WIPPS COUNTRIES WEU+COC

- Designed for countries within WEU+COC

803 YOM X2/1

- Year of manufacture

859 CENTRAL DISPLAY SIZE M

- Central display size is medium

877 AMBIENT LIGHTING

- Ambient lighting feature

8B6 PARK ASSIST WITH CROSS-TRAFFIC FUNCTION (UN R79)

- Park assist with cross-traffic function

8U8 I-SIZE MARKING (ISOFIX SUCCESSOR)

- I-Size marking for child seat attachment

942 LOAD COMPARTMENT/TRUNK PACKAGE

- Package for the load compartment/trunk

971 EXHAUST SYSTEM WITH DPF, GENERATION 1.5

- Exhaust system with DPF, generation 1.5

98B UPPER RADIATOR SHUTTERS

- Includes upper radiator shutters

B09 REFRIGERANT COMPRESSOR WITH MAGNETIC CLUTCH

- Refrigerant compressor with magnetic clutch

B59 DRIVE PROGRAM SELECTION SWITCH (AGILITY SELECT)

- Drive program selection switch for Agility Select

F247 MODEL SERIES 247

✦✦ Belongs to model ser

GA AUTOMATIC TRANSMISSION

✦✦ Equipped with automatic tra

HA REAR AXLE

✦✦ Rear axle configu

L LEFT-HAND DRIVE

✦✦ Left-hand drive config

M013 DERATED ENGINE

✦✦ Engine is derated for specific p

M654 INLINE DIESEL ENGINE OM654

✦✦ Inline diesel engine

P44 PARKING PACKAGE

✦✦ Parking assistance p

PXV CONTROL CODE FOR SALES

✦✦ Control code used for sales

PYD CONTROL CODE FOR SALES

✦✦ Sales control

R01 SUMMER TYRES

✦✦ Summer tires equ

R7D WHEEL SIZE 17" "ALL-ROUND VARIANT 1"

✦✦ 17-inch wheels - Variant 1, suitable for

U10 FRONT PASSENGER SEAT WITH WEIGHT SENSOR

✦✦ Front passenger seat with we

U35 12 V SOCKET IN LOAD COMPARTMENT

✦✦ 12V socket in the load con

U54 COMPOUND-LINK AXLE

✦✦ Features compound-

U62 EXTERIOR LIGHT AND SIGHT PACKAGE

✦✦ Comes with exterior light and

V50 SPEED + LOAD INDEX 91W

✦✦ Tire specification: Speed + lo

VR RIGHT FRONT AXLE HALF

✦✦ Right front axle a

FW SEDAN

✦✦ Body type: Se

H61 TRIM ELEMENTS - PLASTIC IMD FADING MESH (2B83)

✦✦ Plastic trim elements with IMD fading

K13 CONTROL CODE FOR SERVICE INTERVAL 25000 KM

✦✦ Service interval control code :

L3E SPORT STEERING WHEEL - SMOOTH SPLIT LEATHER

✦✦ Sport steering wheel with smooth

M20 DISPLACEMENT 2.0 LITER

✦✦ 2.0-liter engine displa

P27 STYLE PACKAGE

✦✦ Style package included for add

P49 MIRROR PACKAGE

✦✦ Mirror package speci

PYA CONTROL CODE FOR SALES

✦✦ Control code used for sales

PYN CONTROL CODE FOR SALES

✦✦ Control code used for sales

R04 LIGHT-ALLOY WHEEL 5-DOUBLE-SPOKE DESIGN 17" "ALL-ROUND"

✦✦ 17-inch alloy wheels with a 5-double-spoke design for all sides

U01 REAR SEAT BELT STATUS INDICATOR

✦✦ Indicator for rear seat b

U12 VELOUR FLOOR MATS

✦✦ Includes velour flo

U45 ILLUMINATED DOOR SILL WITH EXCHANGEABLE COVER

✦✦ Illuminated door sill with exchang

U59 SEAT COMFORT PACKAGE

✦✦ Includes seat comfort

U79 BLUETEC SCR DIESEL EXHAUST GAS CLEANING, GENERATION 3

✦✦ Equipped with BLUETEC SCR diesel exhaust gas

VL LEFT FRONT AXLE HALF

✦✦ Left front axle a:

Vremenska crta

Pronađena 3 zapisa

Vremenska crta zapisa za ovo vozilo

● 09. 2022. 🌐 Država nepoznata

Proizvedeno

Zabilježen je datum proizvodnje ovog vozila. Navedena zemlja može ukazivati na mjesto proizvodnje ili registracije.

● 09. 2022. 🇫🇷 Francuska

Registrirano

Za ovo vozilo dodan je zapis o registraciji. To može biti zbog prve registracije, promjene vlasništva ili druge službene dokumentacije.

● 11. 2025. 🇫🇷 Francuska

Na prodaju

Zapis oglasa pokazuje da je ovaj automobil bio oglašen na prodaju. Ponekad se navedena zemlja može razlikovati od stvarne lokacije vozila.



+36

Izvori podataka

Provjerili smo 900+ izvora podataka u **40 država**

Korisni savjeti nakon čitanja izvješća

Svaki savjet koji primijeniš pomoći će ti da izbjegnute neželjena iznenađenja kasnije. Što bolje provjeriš, to je kupnja sigurnija.

Provjeri povijest vozila

To je već obavljeno? Sjajan početak! Evo što trebaš učiniti dalje:

- Iskoristi savjete iz ovog odjeljka kada osobno pregledavaš automobil.
- Označi ih i uvjeri se da ne propuštaš nešto važno.

Zatraži pregled stručnjaka

Iskusni mehaničar može uočiti skrivene probleme koji bi tebi mogli promaći. Evo što trebaš učiniti dalje:

- Naruči provjeru u neovisnom ili ovlaštenom servisnom centru
- Zamoli mehaničara da provjeri ključne sustave: motor, kočnice, ovjes, elektroniku
- Zatraži pisane bilješke ili izvješće o svim pronađenim problemima

Provjeri kilometražu

Provjeri odgovara li kilometraža u ovom izvješću očitavanju brojača kilometara automobila. Tvoja zadnja poznata kilometraža je **91.917 km**. Evo što trebaš učiniti dalje:

- Napravi usporedbu očitavanja brojača kilometara i kilometraže navedene u izvješću
- Potraži znake lažiranja (istrošene papučice, sumnjivi popravci na kontrolnoj ploči)
- Zatraži objašnjenje za sve što izgleda sumnjivo

Zatraži evidenciju o servisiranju

Evidencija o servisiranju pokazuje koliko je automobil dobro održavan. Evo što trebaš učiniti dalje:

- Zatraži od prodavača knjižicu servisa ili evidenciju održavanja automobila
- Provjeri jesu li ulje i filtri redovito mijenjani i kakvo je stanje zupčastog remena
- Obrati pažnju na sve servise koje nedostaju ili kasne

Obavi pravu probnu vožnju

Pravilna probna vožnja pomoći će ti da uočiš probleme s performansama, upravljanjem ili udobnošću – primijetit ćeš puno više na cesti nego na parkiralištu. Evo što trebaš učiniti dalje:

- Vozi autocestom
- Vozi neravnim ili lošim cestama
- Vozi u gradskom prometu
- Osluškuj čudne zvukove ili vibracije
- Obrati pažnju na upravljivost i udobnost

Napravi usporedbu sa sličnim automobilima

Provjerom drugih oglasa vidjet ćeš je li tražena cijena poštena ili isplati li se uopće pregovarati. Evo što trebaš učiniti dalje:

- Pretraži slične automobile online (ista marka, model, godina, kilometraža)
- Usporedi tražene cijene
- Provjeri stanje i opremu automobila
- Iskoristi ove informacije u pregovorima s prodavačem