

## Peugeot 2008

Skeniraj za cjelovito izvješće



Broj šasijske: VF3CUHMZ6JY058202

Gorivo: Benzin

Godina: 2018

Vrsta mjenjača: Ručni

## Kilometraža

✔ Nisu pronađeni problemi

Posljednja zabilježena kilometraža: 39.002 km.

## Provjera pravnog statusa

✔ Nisu pronađeni problemi

Nisu pronađeni zapisi o financijskim ili pravnim rizicima.

## Oštećenje

✔ Nisu pronađeni problemi

Nisu pronađeni zapisi o oštećenjima ili procjeni.

## Krađa

✔ Nisu pronađeni problemi

Nema podataka o krađi.

## Emisije

✔ Nisu pronađeni problemi

Niska razina CO<sub>2</sub> emisija: 114 g/km.

## Izloženost prirodnim katastrofama

✔ Nisu pronađeni problemi

Nisu pronađeni zapisi o izloženosti prirodnim katastrofama.



+44

## Izvori podataka

Provjerili smo 1000+ izvora podataka u 48 država

## Krađa

Provjerili smo je li vozilo trenutno navedeno kao ukradeno, je li ikada u prošlosti prijavljeno kao ukradeno i je li pronađeno.



## Nije pronađen nijedan problem

Nismo pronašli nikakve podatke da je vozilo ukradeno.



## Sažetak

Provjera baze podataka ukradenih vozila izvršena je u 7 država: +1

## Evo što smo provjerili:



Traži li se trenutno kao ukradeno?

✔ Podaci nisu pronađeni



Je li vozilo bilo ukradeno u prošlosti?

✔ Podaci nisu pronađeni

Za ovo vozilo nisu pronađeni zapisi o krađama u prošlosti.

## Provjera policijske baze podataka ukradenih vozila izvršena je u sljedećim državama:


Češka Italija Slovenija Mađarska Slovačka Rumunjska Kanada

# Kilometraža

Provjerili smo je li kilometraža točna ili je možda bila lažirana.

## Sažetak

- Posljednja poznata kilometraža: 39.002 km
- Pronađena su 3 zapisa o kilometraži



## Zapisi brojača kilometara

04. 2018.	13 km
04. 2022.	25.221 km
04. 2024.	39.002 km

## Očekivana trenutna kilometraža

Na temelju nedavnih vozačkih navika, trenutna kilometraža može biti **oko 52.884 km**. Stvarna kilometraža može se razlikovati – provjeri brojač kilometara automobila radi točnosti.

## Vozačke navike

04. 2018.	- 04. 2024.	<span style="color: blue;">■</span> Uobičajena vožnja	536 km/mjeseč
-----------	-------------	---	---------------

# Provjera pravnog statusa

Provjerili smo je li vozilo prošlo tehničke preglede i je li označeno kao otpad.

- ✓ Nije pronađen nijedan problem  
Nisu pronađeni podaci o pravnom statusu ovog vozila

## Pravni status

- ✓= Je li vozilo prošlo tehnički pregled? ✓ Podaci nisu pronađeni
- ↺↻ Je li bilo označeno kao otpad? ✓ Podaci nisu pronađeni

## Preporučeni raspored servisiranja

Za sve detalje o prošlim i sljedećim servisima pregledaj digitalno izvješće.

### i Sažetak

- Zadnje planirano održavanje bilo je prije 14.002 km – provjeri koje je održavanje bilo potrebno
- Na temelju zabilježene kilometraže, sljedeći preporučeni servis je na 10.998 km

## Sljedeći preporučeni servis na 50.000 km

### Što treba servisirati:

#### 🕒 Približno vrijeme trajanja servisiranja 60 min

Filter ulja motora (Zamijenite) Kotači (Skinite/montirajte) +53 stavki servisiranja

#### 🕒 Približno vrijeme trajanja servisiranja 6 min

Filtar kabine (ako ga ima) (Zamijenite)

#### 🕒 Približno vrijeme trajanja servisiranja 24 min

Korištenje vozila/rad/performance (Provjerite/obavijestite)

#### 🕒 Približno vrijeme trajanja servisiranja 18 min

Filter za zrak (Zamijenite) Svjećice (Zamijenite)

## Prethodni preporučeni servis na 25.000 km

### Što je trebalo servisirati:

#### 🕒 Približno vrijeme trajanja servisiranja 60 min

Filter ulja motora (Zamijenite) Kotači (Skinite/montirajte) +53 stavki servisiranja

#### 🕒 Približno vrijeme trajanja servisiranja 6 min

Filtar kabine (ako ga ima) (Zamijenite)

## Oštećenje

Je li ovo vozilo bilo oštećeno u prošlosti? Kolika je bila vrijednost štete?

- ✓ **Nije pronađen nijedan problem**  
Nisu pronađeni zapisi o oštećenjima ili procjeni



Ponekad mogu biti prikazane netočne informacije, posebno u slučaju provjere starijih vozila. Neovlašteni servisi mogu ilegalno zamaskirati nedostatke ili oštećenja na vozilu, a da pritom nisu nigdje zabilježena. Ponekad može biti zamijenjena čak i pločica s brojem šasije vozila. Koristimo različite metode da bismo otkrili takve prekršaje, ali nemoguće je dati 100 %-tnu garanciju.


## Izloženost prirodnim katastrofama

Provjerili smo je li se vozilo nalazilo u području pogođenom prirodnim katastrofama u trenutku kada su se dogodile.

- ✓ **Nije pronađen nijedan problem**  
Lokacija ovog vozila nije zabilježena na području prirodnih katastrofa.

## Emisije

Analizirali smo koliko CO<sub>2</sub> ovaj model automobila obično proizvodi i koji se porezi ili naknade mogu primjenjivati.

-  **carVertical uvid**  
Ovo vozilo ima niske emisije. Može se kvalificirati za niže poreze na emisije. Provjeri lokalne propise i vidi vrijede li popusti.

## Emisije CO<sub>2</sub>

114 g/km Razred: **A**



## Specifikacije & oprema

Tehničke specifikacije vozila i originalna oprema u zapisu.

Ovaj odjeljak sadrži pojednostavljene opise generirane uz pomoć umjetne inteligencije koji će ti pomoći da bolje razumiješ svaku značajku vozila.



### Sažetak

Provjeri odgovaraju li specifikacije i oprema vozila onome što ti je rekao prodavač.

## Identifikacija i tehničke specifikacije



Proizvođač  
**Peugeot**



Model  
**2008**



Opis  
**2008**



Vrsta karoserije  
**SUV**



Godina proizvodnje  
**2018**



Godina modela  
**2018**



Zapremnina pogonskog sklopa  
**1,2 l**



Snaga pogonskog sklopa  
**60 kW (80 hp / 82 PS)**



Vrsta goriva  
**Benzin**



Vrsta prijenosa  
**Ručni**



Vrsta pogona  
**Pogon na prednje kotače (FWD)**



Boja  
**Siva**



Broj vrata  
**5**



Položaj volana  
**Volan na lijevoj strani upravljačke konzole**



Naziv prijenosa  
**BVM MA5 / N**

## Oprema

Kako je primljeno od proizvođača

**NORMAL**

Normal

**1815** 15114 88 1 0599

**4110** 11/04/2018

Manufacturing date: 11/04/2018

**7610** 9807196799

Identification number: 9807196799.

**8411** 2008 (A94F)

2008 (A94F)

**AAEA18** ALTERNATOR 120 AMP

120 amp alternator

**ACNLU29** ANALOGUE CONNECTED NAVIGATION

Analog navigation system with connected features

**AESML24** 68 AMP ELECTRIC STEERING

68 amp electric steering

**AF0E23** 1 100W AERO 2-SPEED FAN

Aero 2-speed fan with 100W power

**AFYCF20** AIRCON FLUID 1234 YF

Air conditioning fluid 1234 YF

**AIRWIRGOT42** AUTO INTERMITTENT RR WIPER IN REVERSE

GEAR

Automatic intermittent rear wiper while in reverse gear

**ARXET18** AXLE RATIO 13 X 64

Equipped with a 13 × 64 axle ratio

**AWADT44** "EOBD" AUTO-DIAGNOSTIC WITHOUT ACCELEROMETER

✦ Auto-diagnostic system without accelerometer

**B2015** 10 B217 0445760

**BCEHYL27** BODY COLOUR EXTERIOR HANDLE

✦ Body-colored exterior handles

**BCMTR15** BOOT CARPET MAT

✦ Boot carpet mat

**BDDM17** BAR DIAMETER 20.5

✦ This vehicle has a bar with a diameter of 20.5 inches.

**BMNMN11** BVM MA5 / N

✦ BVM MA5/N manual transmission

**BWTPW19** BUMPER WITHOUT TRIM

✦ Bumper without trim

**CCASLGM45** PROGRAMMABLE CRUISE CONTROL AND SPEED LIMITER

✦ Cruise control and speed limiter that can be programmed

**CDTCDS33** CONDENSER 16 DM - THICKNESS 12 CM

✦ Condenser with a diameter of 16mm and thickness of 12cm

**CFIDHOF32** CHROME FINISH INSIDE DOOR HANDLE

✦ Chrome finish inside door handle

**CPVRTL37** CONTROLLED PETROL VAPOUR RECUPERATION

✦ Controlled petrol vapor recuperation

**DABVS15** DRIVERS AIR BAG

✦ Driver's airbag for added safety

**DCRCEC24** DIRECT CAR RADIO CONTROL

✦ Direct car radio control

**AWFEREL33** ASSEMBLY WITHOUT FRONT ELBOW REST

✦ Front armrest assembly not included

**BCC214** BSI + COM 2008

✦ BSI and COM 2008 system

**BCFBCBACRBYL61** BODY COLOUR FR BUMPER + CHROME BEAD AND BODY COLOUR RR BUMPER

✦ Front bumper in body color with chrome bead and rear bumper in body color

**BCSCVDCA44** BLACK CAPPING + SATIN CHROME VENT DECORATION

✦ Black Capping with Satin Chrome Vent Decoration

**BLEETY29** BATTERY L2 640 60AH EF 640 EN

✦ Battery L2 640 60AH EF 640 EN

**BTMCR18** BLACK TREATED MASK

✦ Black treated mask to enhance the vehicle's front appearance

**C038** 1200 CM3

✦ Engine capacity of 1200 cm3

**CCDU14** COLD COUNTRIES

✦ Cold countries specification

**CEMGVE28** CURVED EXTERIOR MIRROR GLASS

✦ Curved exterior mirror glass

**COS25** 5-DOOR 5-SEATER CROSSOVER

✦ Designation: 5-door 5-seater crossover

**CSG13** PASSENGER CAR

✦ Passenger car

**DASBA23** DOUBLE ACCESSORY SOCKET

✦ Double accessory socket

**DDFE24** DIFFERENTIAL DIAMETER 77

✦ Differential with a diameter of 77 units

**DFARCLRCRR48** DOORS + FR AND RR COURTESY LIGHTS

REMOTE CONTROL

✦✦ Remote control of doors and courtesy lights

**DIRMNH28** DAY -NIGHT INNER REAR MIRROR

✦✦ Day-night inner rearview mirror

**DOTRSVG30** DRIVING ON THE RIGHT-HAND SIDE

✦✦ Designed for driving on the right-hand side

**DSWCHVS54** DRIVER'S+PASSENGER'S SIDE WITH CARD

HOLDER+WORDING

✦✦ Driver and passenger side holders with wording

**EDEMCI35** ELECTRIC DRIVER'S EXTERIOR MIRROR

✦✦ Electric driver's side mirror

**EFEMCI32** ELECTRIC FOLDING EXTERIOR MIRROR

✦✦ Electric folding exterior mirrors

**EMEICSG46** PASSENGER EXT MIRROR ELECTRIC INTERIOR

CONTROL

✦✦ Electrically adjustable passenger side mirror controlled from inside the vehicle

**EPSCI23** ELECTRIC POWER STEERING

✦✦ Electric power steering

**ETEYE14** EB TYPE ENGINE

✦✦ EB type engine

**EUCPNOA42** EUROPEAN UNION CONSTRUCTOR'S PLATE +

NRE

✦✦ European Union constructor's plate

**FARFSTRSDR47** FEED AERIAL RECEIV FRT SPEAKER TWT

REAR SPEAKER

✦✦ Feed aerial and front/rear speaker setup

**FHANE25** FRONT HEADREST ADJUSTABLE

✦✦ Adjustable front headrests

**FTWLTLN30** FUEL TANK WITHOUT LOCATING TAB

✦✦ Fuel tank without locating tab

**DHAAE23** PARALLEL DRV HEIGHT ADJ

✦✦ Height adjustable parallel driver's seat

**DOOWLVC33** DRIV OCCULT+PASS OCCULT W/O LIGHT

✦✦ Driver and passenger occult lighting

**DSFD7C26** DGT7C SCREEN FRONT DISPLAY

✦✦ Front display screen with digital design

**E0418** e2\*2007/46\*0070\*39

✦✦ Manufacturer reference number for vehicle approval

**EEEOE32** EURO 6.1 ENGINE EMISSION CONTROL

✦✦ Euro 6.1 engine emission control

**EIFK19** EB2F 60KW INJECTION

✦✦ EB2F 60kW injection engine

**EPGPPT25** EVL - PLATINUM GREY PAINT

✦✦ EVL - Platinum Grey paint

**ESPCO28** ELECTRONIC STABILITY PROGRAM

✦✦ Electronic stability program

**ETMTE16** ESP TEVES MK100E

✦✦ ESP Teves MK100E system

**EVTECOV43** EURO 6.1 VEHICLE TECHNICAL EMISSION

CONTROL

✦✦ Euro 6.1 vehicle technical emission control

**FDRLNA33** FRONT DAYTIME RUNNING LAMPS (DRL)

✦✦ Front daytime running lamps

**FSTFRSSA41** 4 FR SPEAKERS (2 TW + 2 FR)+2 RR SPEAKERS

✦✦ 4 front speakers and 2 rear speakers system

**FWRUDTG31** FITTING WITH RR UPPER DEFLECTOR

✦✦ Rear upper deflector fitting

**GBDBCSSL39** GLOSS BLACK DECOR + BODY COLOUR

**SPOILER**

✦✦ Comes with gloss black decor and a body color spoiler.

**GTDR12** GOOD TERRAIN

✦✦ Good terrain capability

**HEMTE22** HEATED EXTERIOR MIRROR

✦✦ Heated exterior mirrors

**HPKSMKPP33** 1 HF PLIP KEY + 1 SINGLE MAIN KEY

✦✦ 1 HF plip key and 1 single main key provided

**IEI9** INJECTION

✦✦ Standard fuel injection system

**ITACPTH37** IHX TECHNOLOGY AIR CONDITIONING PIPES

✦✦ IHX technology air conditioning pipes

**ITUDWLIC56** INDIRECT TYRE UNDER-INFLATION DETECTION  
WITHOUT LOCATION

✦✦ Indirect tyre under-inflation detection system

**JSUCO19** 1 JACK SOCKET + USB

✦✦ Jack socket and USB port

**KPGNP20** PU KNOB + PVC GAITER

✦✦ Interior decoration with a PU knob and a PVC gaiter

**LRCFMHKG54** LOCKING REMOTE CONTROL FREQUENCY  
433.92 MHZ HETERODYNE

✦✦ Remote control with locking feature operating at 433.92 MHz frequency

**LWSWARTIT53** LAMINATED WINDSCREEN + SIDE WINDOW  
AND REAR TOUGHENED

✦✦ Laminated windscreen, side windows, and toughened rear window

**MBRSTTA29** MATT BLACK REAR SURROUND TRIM

✦✦ Matt black rear trim

**GT7** PEUGEOT

✦✦ Manufactured by Peugeot

**HCRL16** HYDRAULIC CLUTCH

✦✦ Hydraulic clutch mechanism

**HLHW8** HIGH LOW

✦✦ High and low settings

**HSNA13** HORN STANDARD

✦✦ Standard horn

**ISEE17** INJECTED SPECKLED

✦✦ Injected speckled finish

**ITFNT20** 16 INCH TYRE FITMENT

✦✦ 16-inch tyre fitment

**IWWWLIEI66** 2-SPEED INTERMITTENT WINDSCREEN WIPE  
WITHOUT WATER LEVEL INDICATOR

✦✦ Intermittent windscreen wipe without water level indicator

**KNE018** POWER 60 KW 118 NM

✦✦ This vehicle has a power output of 60 kW and torque of 118 Nm.

**LDTN15** LEFT-HAND DRIVE

✦✦ Left-hand drive

**LSIU18** LUMINOUS SIGNATURE

✦✦ Luminous signature

**MADUA26** MANUAL AIRBAG DEACTIVATION

✦✦ Manual airbag deactivation feature

**MFPSCUF35** MANUAL FRONT PASSENGER SEAT CONTROL

✦✦ Manual front passenger seat control

**MLE8 MID-LIFE**

✦✦ Mid-life upgrade

**MRCLUR22 MANUAL REAR CHILD LOCK**

✦✦ Manual rear child lock

**MSOOLUS29 MANUAL SWITCHING ON OF LIGHTS**

✦✦ Manual light control switch

**NAAE12 NOT AFFECTED**

✦✦ Not affected by particular feature

**NAMA17 NORMAL ATMOSPHERE**

✦✦ Normal atmosphere conditioning

**NFCOMF36 NORMAL FUEL CONSUMPTION OPTIMISATION**

✦✦ Normal fuel consumption optimization

**NSMS17 NORMAL SUSPENSION**

✦✦ Normal suspension

**RDSBLI30 RECLINING DRIVER'S SEAT BACK**

✦✦ Reclining driver's seat back

**RFCMN45 3-COMPONENT RHODIUM+PLATINUM FILTER CATALYSER**

✦✦ 3-component rhodium and platinum filter catalyzer

**RHARA24 REAR HEADREST ADJUSTABLE**

✦✦ Adjustable rear headrests

**RRWIO20 6,5" RIM ROAD WHEELS**

✦✦ 6.5" road wheels

**RSWSTUD35 REDUCED STEEL WHEEL + STANDARD TYRE**

✦✦ Steel wheel with standard tires

**SBWAOC32 PYROTECHNIC SEAT BELT WITH ALARM**

✦✦ Seat belt with alarm system triggered by pyrotechnics

**MPAI18 METALLIC PAINTWORK**

✦✦ Metallic paintwork

**MRHNR22 MOUNT 3 REAR HEAD-REST**

✦✦ Mounting for 3 rear headrests

**MWRBNN23 MOUNTING WITH ROOF BARS**

✦✦ Roof bars for mounting purposes

**NALMA26 NORMAL + AUTOMATIC LOCKING**

✦✦ Normal and automatic locking system

**NCSIT27 NAVIGATION 2 COLOUR SCREENS**

✦✦ Navigation system with 2 color screens

**NHSHT15 NON HEATED SEAT**

✦✦ Non-heated seats

**ODFWTC30 ONE-TOUCH DRIVER'S FR WINDOW**

✦✦ One-touch driver's front window control

**RESWLRE41 REAR ELECTRIC SEQUENTIAL WINDOW + LOCKING**

✦✦ Rear electric sequential window control with locking feature

**RFIEO25 RESERVOIR FILTER INTERIOR**

✦✦ Reservoir filter interior

**RROSRD26 REAR RADAR OBSTACLE SENSOR**

✦✦ Rear radar obstacle sensor

**RSBEP31 3-REEL, 3-POINT REAR SEAT BELTS**

✦✦ 3-reel, 3-point rear seat belts

**SACGA23 SINGLE AIR CONDITIONING**

✦✦ Single air conditioning system

**SCPFWLUC42 SEQUEN CONTROL PASSENG FRONT WINDOW LIFTER**

✦✦ Sequential control for passenger front window lifter

**SEOGE21 SINGLE EXHAUST OUTLET**

✦✦ Single exhaust outlet

**SGIKER24 SPEED GRADUATION IN KM/H**

✦✦ Speed graduation in km/h

**SMCRR18 STARTER MOTOR CL 3**

✦✦ Starter motor Class 3

**SRARO17 SHORT ROOF AERIAL**

✦✦ Short roof aerial antenna

**SSPBPS29 SIMPLE STANDARD PEDAL BRACKET**

✦✦ Standard pedal bracket

**STL9 16" STEEL**

✦✦ 16-inch steel wheels

**TODYR28 TOKYO + ORNIS + DUBLING "59"**

✦✦ Features a combination of Tokyo, Ornis, and Dubling design elements.

**TRNRE534 TYRE 195/60 R16 89H NON REINFORCED**

✦✦ 195/60 R16 89H non-reinforced tires

**UBSEO36 UNDERBONNET + BULKHEAD SOUNDPROOFING**

✦✦ Soundproofing under the bonnet and bulkhead

**VFDDTA33 VENTILATED FRONT DISCS/REAR DISCS**

✦✦ Ventilated front discs/rear discs

**WABHS15 WITH ABS BRAKES**

✦✦ Equipped with ABS brakes

**WAOPSHR29 WITH AIRBAG ON PASSENGER SIDE**

✦✦ Airbag on passenger side

**WBCMHT31 WITH BATTERY CHARGE MEASUREMENT**

✦✦ With battery charge measurement

**W BSPHT28 WITHOUT BODY SILL PROTECTORS**

✦✦ Without Body Sill Protectors

**SFBBSAT29 SEPARATE FOLD BACK BENCH SEAT**

✦✦ Separate fold-back bench seat

**SHKNR23 STANDARD HANDBRAKE KNOB**

✦✦ Standard handbrake knob

**SMTEN28 STEERING MECHANISM TRAVEL 70**

✦✦ Steering mechanism travel limit of 70

**SSBNR21 STANDARD SIDE BUMPERS**

✦✦ Standard side bumpers

**SSWNN23 STANDING STEERING WHEEL**

✦✦ Equipped with a standing steering wheel.

**SWEH12 STEEL WHEELS**

✦✦ Steel wheels provided

**TRDBAWMHK49 16 THICK RADIATOR - 16 DM2 BRAZED ALU****WITHOUT MEC**

✦✦ 16 thick radiator with 16 DM2 brazed aluminum construction (without mechanical)

**TSCARS28 THORAX SIDE + CURTAIN AIRBAG**

✦✦ Includes thorax side and curtain airbags

**UPQAE35 UNLEADED PETROL 95 QUALITY A/B/E/E+**

✦✦ Unleaded Petrol 95 quality A/B/E/E+

**VISEN22 VALEO INJECTION SYSTEM**

✦✦ Valeo injection system

**WADHT29 WITHOUT ANTI-POLLUTION DEVICE**

✦✦ Vehicle without an anti-pollution device

**WASWAEHS44 WITH ABSOLUTE STEERING WHEEL ANGLE ESTIMATOR**

✦✦ Absolute steering wheel angle estimator

**WBHT13 WITHOUT BADGE**

✦✦ Without Badge

**WBTOT13 W/O BOOT TIDY**

✦✦ Without boot tidy storage

**WCAE13** W/O CARPETMAT

✦✦ Without carpet floor mats

**WCHT18** WITHOUT CONVERSION

✦✦ Without conversion

**WCSAO22** W/O CAB SOUND-PROOFING

✦✦ Without cabin soundproofing

**WDELRHT37** WITH DETACHABLE EXTERIOR LASHING RING

✦✦ Detachable exterior lashing ring

**WDSLHT26** WITHOUT DOOR SILL LIGHTING

✦✦ Without door sill lighting

**WEOEXU30** W/O EXHAUST OUTLET EMBELLISHER

✦✦ Without exhaust outlet embellisher

**WERFTN30** WESTERN EUROPE RADIO FREQUENCY

✦✦ Western Europe radio frequency

**WFBHT20** WITHOUT FULLER BADGE

✦✦ No Fuller badge

**WFFHO19** WITH FRONT FOGLAMPS

✦✦ Front fog lamps installed

**WHEEE18** W/O HELP EQUIPMENT

✦✦ No help equipment provided

**WHWEL18** W/O HEADLAMP WIPER

✦✦ Without headlamp wiper

**WLPHT21** WITHOUT LICENCE PLATE

✦✦ Without license plate

**WMHT16** WITHOUT MUDGUARD

✦✦ No mudguards installed

**WCDHT20** WITHOUT COMPACT DISC

✦✦ Without compact disc player

**WCIPST146** WHITE CIRCLE INSTRUMENT PANEL+PAINTED SURROUND

✦✦ White circle design on instrument panel with painted surround

**WCSMWIRHT39** WITHOUT CHILD SEAT MOUNTING WITH ISO RR

✦✦ Child seat mounting without ISO rear

**WDFWDHT36** WITHOUT DIESEL FILTER WATER DETECTOR

✦✦ Without diesel filter water detector

**WEAHT27** WITHOUT EQUALISER AMPLIFIER

✦✦ Without equalizer amplifier

**WEPQP18** W/O EQUIPMENT PACK

✦✦ Without equipment pack

**WEUNN24** W/O ENGINE UNDERSHIELDING

✦✦ Without engine undershielding

**WFBPHT25** WITHOUT FRONT BUMPER PLUG

✦✦ Front bumper plug not included

**WGLHT25** WITHOUT GLOVEBOX LIGHTING

✦✦ This vehicle does not have interior glovebox lighting

**WHT7** WITHOUT

✦✦ None

**WLHT13** WITHOUT LABEL

✦✦ Without label

**WLTMHT37** WITHOUT LATERAL TRAJECTORY MONITORING

✦✦ No lateral trajectory monitoring

**WMIAHT42** WITHOUT MISCELLANEOUS INTERIOR ACCESSORIES

✦✦ Without miscellaneous interior accessories

**WMLHR16** WITH MIRROR LINK

✦✦ With mirror link feature

**WMRLAE20** W/O MAP READING LAMP

✦✦ No map reading lamp installed

**WPDPDG39** PADDING WITHOUT PASSENGER DETECTION PAD

✦✦ Padding without passenger detection pad

**WPNRE18** W/O PROTECTING NET

✦✦ Without protecting net

**WPUBHT29** WITHOUT PROTECTION UNDER BODY

✦✦ No protection under the body

**WRLHE22** WITH 1 REVERSING LIGHT

✦✦ Reversing light

**WSASHT22** WITHOUT STOP AND START

✦✦ Without stop and start system

**WSCHT19** WITHOUT SPEED CHECK

✦✦ Without speed check

**WSGCRHM31** WITH SUMP GAS CIRCUIT REHEATING

✦✦ Sump gas circuit reheating

**WSRHT25** WITHOUT SPEEDOMETER RATIO

✦✦ No speedometer ratio adjustment

**WTDT13** WINDOW TINTED

✦✦ Tinted windows

**WTPAHT30** WITHOUT THEFT PROTECTION ALARM

✦✦ Without theft protection alarm

**WWHF9** WITH WIFI

✦✦ With WiFi connectivity

**WWTHT24** WITHOUT WARNING TRIANGLE

✦✦ Without warning triangle

**WMMHT27** WITHOUT MINOR MODIFICATIONS

✦✦ No minor modifications

**WOLIE23** W/O OIL LEVEL INDICATOR

✦✦ No oil level indicator

**WPFHT23** WITHOUT PARTICLE FILTER

✦✦ Without particle filter

**WPSALSHT46** WITHOUT PASSENGER'S SIDE AND LUMBAR SUPPORTS

✦✦ Does not have passenger's side and lumbar supports

**WRLFHT23** WITHOUT REAR LOAD FLOOR

✦✦ Without rear load floor

**WRWHT19** WITHOUT ROOF WINDOW

✦✦ Without roof window

**WSBE15** W/O SETTING BOX

✦✦ Does not include a setting box.

**WSDEHT26** WITHOUT SEAL DIRT EXCLUDER

✦✦ No seal dirt excluder included

**WSPSHT29** WITHOUT SPACER PASSENGER SIDE

✦✦ No spacer on the passenger side

**WTAHL18** 16" WHEEL TRIM A94

✦✦ 16-inch wheel trim in A94 design

**WTHT14** WITHOUT TOWBAR

✦✦ Without towbar

**WTUHT22** WITHOUT TELEMATIC UNIT

✦✦ No telematics unit

**WWJWDDI33** WINDSHIELD WASHER JET W/O DEFROST

✦✦ Windshield washer jet without defrost

# Vremenska crta

Pronađeno 5 zapisa

Vremenska crta zapisa za ovo vozilo

- 04. 2018.  Država nepoznata

## Proizvedeno

Zabilježen je datum proizvodnje ovog vozila. Navedena zemlja može ukazivati na mjesto proizvodnje ili registracije.

- 04. 2018.  Francuska

## Prva registracija

Za ovo vozilo dodan je zapis o registraciji. To može biti zbog prve registracije, promjene vlasništva ili druge službene dokumentacije.

- 09. 2019.  Francuska

## Registrirano

Za ovo vozilo dodan je zapis o registraciji. To može biti zbog prve registracije, promjene vlasništva ili druge službene dokumentacije.

- 04. 2022.  Francuska

## Pregledano

Za ovo vozilo je zabilježen tehnički pregled. To može uključivati razne provjere vezane uz tehničku ispravnost ili emisije. Mogu se uključiti i uspješni i neuspješni pregledi.

- 04. 2024.  Francuska

## Pregledano

Za ovo vozilo je zabilježen tehnički pregled. To može uključivati razne provjere vezane uz tehničku ispravnost ili emisije. Mogu se uključiti i uspješni i neuspješni pregledi.



+44

## Izvori podataka

Provjerili smo 1000+ izvora podataka u **48 država**

## Korisni savjeti nakon čitanja izvješća

Svaki savjet koji primijeniš pomoći će ti da izbjegnute neželjena iznenađenja kasnije. Što bolje provjeriš, to je kupnja sigurnija.

Prije kupnje automobila provjeri sljedeće:

### Zatraži pregled stručnjaka

Iskusni mehaničar može uočiti skrivene probleme koji bi tebi mogli promaći. Evo što trebaš učiniti dalje:

Naruči provjeru u neovisnom ili ovlaštenom servisnom centru

Zamoli mehaničara da provjeri ključne sustave: motor, kočnice, ovjes, elektroniku

Zatraži pisane bilješke ili izvješće o svim pronađenim problemima

### Zatraži evidenciju o servisiranju

Evidencija o servisiranju pokazuje koliko je automobil dobro održavan. Evo što trebaš učiniti dalje:

Zatraži od prodavača knjižicu servisa ili evidenciju održavanja automobila

Provjeri jesu li ulje i filtri redovito mijenjani i kakvo je stanje zupčastog remena

Obrati pažnju na sve servise koje nedostaju ili kasne

### Provjeri kilometražu

Provjeri odgovara li kilometražu u ovom izvješću očitavanju brojača kilometara automobila. Evo što trebaš učiniti dalje:

Napravi usporedbu očitavanja brojača kilometara i kilometraže navedene u izvješću

Potraži znake lažiranja (istrošene papučice, sumnjivi popravci na kontrolnoj ploči)

Zatraži objašnjenje za sve što izgleda sumnjivo

### Obavi pravu probnu vožnju

Pravilna probna vožnja pomoći će ti da uočiš probleme s performansama, upravljanjem ili udobnošću – primijetit ćeš puno više na cesti nego na parkiralištu. Evo što trebaš učiniti dalje:

Vozi se različitim vrstama cesta: autocestama, gradskim prometom i neravnim ili grubim površinama

Osluškuj čudne zvukove ili vibracije

Obrati pažnju na upravljivost i udobnost

### Napravi usporedbu sa sličnim automobilima

Provjerom drugih oglasa vidjet ćeš je li tražena cijena poštena ili isplati li se uopće pregovarati. Evo što trebaš učiniti dalje:

Pretraži slične automobile online (ista marka, model, godina, kilometraža)

Usporedi tražene cijene

Provjeri stanje i opremu automobila

Iskoristi ove informacije u pregovorima s prodavačem