

Mercedes-Benz GLA 180

Skeniraj za cjelovito izvješće



Broj šasijske: W1N2477101J355437

Vrsta karoserije: SUV

Gorivo: Dizel

Vrsta mjenjača: Automatski

Zapremnina motora: 2 l

Snaga pogonskog sklopa: 85 kW (114 hp / 116 PS)

Kilometraža

✔ Nisu pronađeni problemi

Posljednja zabilježena kilometraža: 149.574 km.

Provjera pravnog statusa

✔ Nisu pronađeni problemi

Nisu pronađeni zapisi o financijskim ili pravnim rizicima.

Oštećenje

✔ Nisu pronađeni problemi

Nisu pronađeni zapisi o oštećenjima ili procjeni.

Krađa

✔ Nisu pronađeni problemi

Nema podataka o krađi.



+44

Izvori podataka

Provjerili smo 1000+ izvora podataka u 48 država

Krađa

Provjerili smo je li vozilo trenutno navedeno kao ukradeno, je li ikada u prošlosti prijavljeno kao ukradeno i je li pronađeno.



Nije pronađen nijedan problem

Nismo pronašli nikakve podatke da je vozilo ukradeno.

Evo što smo provjerili:



Traži li se trenutno kao ukradeno?

Nema zapisa koji ukazuju da je ovo vozilo trenutno prijavljeno kao ukradeno i da se za njim traga.



Je li vozilo bilo ukradeno u prošlosti?

Za ovo vozilo nisu pronađeni zapisi o krađama u prošlosti.

Provjera baze podataka ukradenih vozila izvršena je u 7 država:

Slovenija Italija Slovačka Mađarska Rumunjska Češka Kanada


Kilometraža

Provjerili smo je li kilometraža točna ili je možda bila lažirana.



Sažetak

- Posljednja poznata kilometraža: 149.574 km
- Pronađeno je 5 zapisa o kilometraži



Zapisi brojača kilometara

12. 2022.	27.077 km
10. 2023.	58.621 km
09. 2024.	92.211 km
10. 2025.	126.092 km
06. 2026.	149.574 km

Vozačke navike

12. 2022. - 10. 2023.	Intenzivna vožnja	3.114 km/mjeseč
10. 2023. - 06. 2026.	Uobičajena vožnja	2.801 km/mjeseč

Provjera pravnog statusa

Provjerili smo je li vozilo prošlo tehničke preglede i je li označeno kao otpad.



Nije pronađen nijedan problem

Nisu pronađeni podaci o pravnom statusu ovog vozila

Pravni status



Je li vozilo prošlo tehnički pregled?

Nisu pronađeni zapisi o tehničkom pregledu za ovo vozilo.



Je li bilo označeno kao otpad?

Nema zapisa da je ovo vozilo označeno kao otpad.

Oštećenje

Je li ovo vozilo bilo oštećeno u prošlosti? Kolika je bila vrijednost štete?



Nije pronađen nijedan problem

Nisu pronađeni zapisi o oštećenjima ili procjeni



Nisu pronađena oštećenja

Ponekad mogu biti prikazane netočne informacije, posebno u slučaju provjere starijih vozila. Neovlašteni servisi mogu ilegalno zamaskirati nedostatke ili oštećenja na vozilu, a da pritom nisu nigdje zabilježena. Ponekad može biti zamijenjena čak i pločica s brojem šasije vozila. Koristimo različite metode da bismo otkrili takve prekršaje, ali nemoguće je dati 100 %-tnu garanciju.

Tržišna cijena

Provjerili smo kako se tržišna cijena ovog vozila mijenjala tijekom vremena, na temelju dostupnih povijesnih podataka i procjena cijena.

Vremenska crta prikazuje ograničeno razdoblje i ne odražava cijenu vozila tijekom cijelog njegovog životnog vijeka.



Sažetak

- Prosječna tržišna cijena za ovakvo vozilo: 32.000 €
- Budi na oprezu zbog mogućih skrivenih problema ako se vozilo prodavalo po znatno nižoj cijeni od trenutne!




Najviša cijena **36.550 €**

Prosječna cijena **32.000 €**

Najniža cijena **26.899 €**

Kriteriji za procjenu tržišne cijene:



Uvidi u tržišne cijene



Prognoza trenda cijena

Očekuje se da će ovo vozilo izgubiti -51% svoje tržišne cijene u sljedećih 7 godina.



Vrijeme prodaje

Na temelju nedavnih podataka o tržištu, slična vozila se obično prodaju u roku od 12 dana

Napomena: Predviđanja se temelje na trenutnim trendovima na tržištu i povijesnim podacima. Stvarna vrijednost pri preprodaji može se promijeniti zbog promjena na tržištu, stanja, lokacije ili drugih čimbenika.

Emisije

Analizirali smo koliko CO₂ ovaj model automobila obično proizvodi i koji se porezi ili naknade mogu primjenjivati.



carVertical uvid

Ovo vozilo ima prosječne emisije. To će vjerojatno uključivati standardne poreze na emisije.

Emisije CO₂

123 g/km Razred: **B**



Specifikacije & oprema

Tehničke specifikacije vozila i originalna oprema u zapisu.

Ovaj odjeljak sadrži pojednostavljene opise generirane uz pomoć umjetne inteligencije koji će ti pomoći da bolje razumiješ svaku značajku vozila.



Sažetak

Provjeri odgovaraju li specifikacije i oprema vozila onome što ti je rekao prodavač.

Specifikacije vozila



Pregled

Proizvođač

Mercedes-Benz

Model

GLA 180

Vrsta goriva

Dizel

Generacija modela

247

Godina modela

2022

Oznaka proizvođača

GLA 180



Performanse i učinkovitost

Vrsta prijenosa	Vrsta pogona	Zapremnina motora
Automatski	Pogon na prednje kotače (FWD)	2 l
Snaga pogonskog sklopa	Broj cilindara	Emisije CO2
85 kW (114 hp / 116 PS)	4	123 g/km
Vrsta pogonskog sklopa		
Unutarnje izgaranje		



Karoserija i dimenzije

Vrsta karoserije	Broj sjedala	Broj vrata
SUV	5	5
Širina	Međuosovinski razmak	
1.834 mm	2.729 mm	

Oprema

Kako je primljeno od proizvođača

00U Services for remote access	07B Operating instructions and service booklet-French
Includes services for remote access	Operating instructions and service booklet in French
0B2 Vehicle production location Rastatt	1B3 Communication module ECE version
Vehicle produced in Rastatt	ECE version communication module
20U Keyless rental	218 Rear view camera
Keyless rental feature	Includes rear view camera for added visibility
235 Active Parking Assist	243 Active Lane Keeping Assist (camera)
Active parking assist system	Active lane keeping assist with camera technology
249 Automatic dimming inside rearview mirror and outside mirrors	255B Mb-Mobilo with DSB and GGD
Automatic dimming rearview mirror and side mirrors	Mobile service with repair and breakdown assistance
258 Collision warning system with FCW-Stop active brake application	260 Model badge on trunk lid - Omission
Collision warning system with active brake application	Model badge on trunk lid is omitted

270 GPS aerial

✦✦ GPS antenna included

287 Through-loading feature

✦✦ Through-loading feature in the rear

2U1 Radiator shutter

✦✦ Includes a radiator shutter

310 Double cup holder

✦✦ Double cup holder included for convenience

311A Fabric - black / anthracite

✦✦ Black/anthracite fabric

345 rain sensor

✦✦ Rain sensor technology

355 Preinstallation for retrofitting navigation system

✦✦ Preinstallation for retrofitting navigation system available

365 Hard drive navigation

✦✦ Equipped with a hard drive navigation system

3U6 HU country set for ECE/ROW

✦✦ HU country set for ECE/ROW

428 Steering wheel gearshift buttons/steering wheel gearshift paddles - painted

✦✦ Steering wheel with gearshift buttons/paddles painted

446 Touchpad only

✦✦ Touchpad control system included

475 Tire pressure monitor (TPM)

✦✦ Tire pressure monitoring system

4B8 USB adapter cable

✦✦ USB Adapter Cable

502 Multi-year free map updates

✦✦ Free map updates for multiple years

286 Luggage nets to left and right driver seat backrests

✦✦ Luggage nets located behind the driver seat

294 Kneebag

✦✦ Kneebag protection included

2U8 Alternative refrigerant

✦✦ Uses alternative refrigerant

310A Fabric

✦✦ Fabric seats

331B Language of instrument cluster/HU - Dutch

✦✦ Language of instrument cluster and HU in Dutch

351 Ecall emergency call system

✦✦ E-Call emergency call system integrated

362 HERMES communications module LTE

✦✦ Hermes communications module with LTE capabilities

367 Pre-installation for Live Traffic Information

✦✦ Preparation for receiving live traffic information

426 Automatic dual-clutch transmission, 8-speed

✦✦ Includes automatic dual-clutch transmission with 8 speeds

440 Cruise control

✦✦ Cruise control functionality available

458 Instrument cluster display S

✦✦ Instrument cluster display with S design

485 Comfort suspension

✦✦ Comfort suspension included

500 Electrically folding exterior mirrors

✦✦ Exterior mirrors that electrically fold

504 Speed sign recognition

✦✦ Supports speed sign recognition for enhanced safety

513L Belgium

✦ Country group rating for Belgium

51U Headliner, black fabric

✦ Black fabric headliner

543 Sun visor with additional function

✦ Sun visor with additional function included

550 Trailer coupling

✦ Trailer coupling feature

5S9 Reinforced sliding sleeve (8-speed DCT)

✦ Upgraded sliding sleeve for smoother shifting with 8-speed DCT transmission

632 Headlamps, LED, static, right-side traffic

✦ LED headlamps with static function for right-side traffic

6P5 Control code for Sales

✦ Control code used for sales purposes

70B Safety vest - driver

✦ Driver's safety vest provided

73B Roller blind compartment closed

✦ Roller blind compartment provided

79B Pre-installation for digital radio standard DAB/DMB

✦ Preparation for digital radio standard DAB/DMB

7U2 Seat model variant 2

✦ Variant 2 of seat model

859 Central display size M

✦ Central display size is medium

8B6 Park Assist with cross-traffic function (UN R79)

✦ Park assist with cross-traffic function (UN R79)

8U8 i-Size marking (Isofix successor)

✦ I-Size marking for child seat attachment

51B Rating, country group EURO-NCAP

✦ Euro-NCAP country group rating

537 Digital Radio standard DAB (Digi. Audio Broadc.)

✦ Standard digital radio with DAB technology

548 Connect 20 Mid (NTG6)

✦ Connect 20 multimedia system (NTG6)

580 Air-conditioning system

✦ Air-conditioning system equipped

5XXL Europe

✦ Euro-spec vehicle

682 Fire extinguisher

✦ Includes fire extinguisher

6S8 Control code - HERMES 2.1B - country collector

✦ Control code for Hermes 2.1B country collector

725 Roof rails in chrome look

✦ Chrome-look roof rails

775U Iridium silver - Metallic finish

✦ Painted in iridium silver metallic finish

7B4 WIPPS countries WEU+COC

✦ Designed for countries within WEU+COC

802 YoM X1/1

✦ Year of manufacture: 1

873 Seat heaters for driver and front passenger

✦ Heated seats for driver and front passenger

8U6 Assistance system steering wheel control changeover

✦ Assistance system control switch on steering wheel

927 Exhaust treatment, Euro 6 technology

✦ Exhaust system compliant with Euro 6 technology

942 Load compartment/trunk package

Package for the load compartment/trunk included

971 Exhaust system with DPF, generation 1.5

Exhaust system with DPF, generation 1.5

998 Control code for conversion to WLTP with RDE

Control code for conversion to WLTP with RDE

B13 Loading sill protection - Chrome

Chrome loading sill protection is included

B59 Drive program selection switch (Agility Select)

Drive program selection switch for agility select

FH Hatchback

The vehicle is a hatchback in body style

H61 Trim elements - Plastic IMD Fading Mesh (2B83)

Plastic trim elements with IMD fading mesh design

K13 Control code for service interval 25000 km

Service interval control code 25000 KM

L3E Sport steering wheel - Smooth split leather

Sport steering wheel with smooth split leather

M013 Derated engine

Engine is derated for specific performance

M654 Inline diesel engine OM654

Inline diesel engine OM654

P44 Parking Package

Parking assistance package

PXV Control code for Sales

Control code used for sales purposes

PYD Control code for Sales

Sales control code

968 Euro 6 technology COC document - without motor vehicle

registration certificate, part 2

Euro 6 technology COC document without vehicle registration certificate

98B Upper radiator shutters

Includes upper radiator shutters

B09 Refrigerant compressor with magnetic clutch

Refrigerant compressor with magnetic clutch

B51 TIREFIT

Equipped with Tirefit system

F247 Model series 247

Belongs to model series 247

GA Automatic transmission

Equipped with automatic transmission

HA Rear axle

Rear axle configuration

L Left-hand drive

Left-hand drive configuration

M006 Power variant

Power Steering

M20 Displacement 2.0 liter

2.0-liter engine displacement

P27 Style Package

Style package included for added features

P49 Mirror package

Mirror package specification

PYA Control code for Sales

Control code used for sales purposes

PYM Control code for Sales

Sales control code

R01 Summer tyres

✦ Summer tires equipped

R7D Wheel size 17" "all-round variant 1"

✦ 17-inch wheels - Variant 1, suitable for all-around use

U10 Front passenger seat with weight sensor

✦ Front passenger seat with weight sensor

U35 12 V socket in load compartment

✦ 12V socket in the load compartment

U59 Seat comfort package

✦ Includes seat comfort package

U62 Exterior light and sight package

✦ Comes with exterior light and sight package

V05 Speed/load index 99V

✦ Indicates the speed and load index of the tires

VR Right front axle half

✦ Right front axle assembly

R04 Light-alloy wheel 5-double-spoke design 17" "all-round"

✦ 17-inch alloy wheels with a 5-double-spoke design for a stylish look on all sides

U01 Rear seat belt status indicator

✦ Indicator for rear seat belt status

U12 Velour floor mats

✦ Includes velour floor mats

U55 Multi-link axle

✦ Equipped with a multi-link axle

U60 Pedestrian protection - Active hood

✦ Active hood system for pedestrian protection

U79 BlueTEC SCR diesel exhaust gas cleaning, generation 3

✦ Equipped with BLUETEC SCR diesel exhaust gas cleaning generation 3

VL Left front axle half

✦ Left front axle assembly

**Izvori podataka**

Provjerili smo 1000+ izvora podataka u **48 država**

Korisni savjeti nakon čitanja izvješća

Svaki savjet koji primijeniš pomoći će ti da izbjegnute neželjena iznenađenja kasnije. Što bolje provjeriš, to je kupnja sigurnija.

Prije kupnje automobila provjeri sljedeće:

☐

Zatraži pregled stručnjaka

Iskusni mehaničar može uočiti skrivene probleme koji bi tebi mogli promaći. Evo što trebaš učiniti dalje:

☐

Naruči provjeru u neovisnom ili ovlaštenom servisnom centru

☐

Zamoli mehaničara da provjeri ključne sustave: motor, kočnice, ovjes, elektroniku

☐

Zatraži pisane bilješke ili izvješće o svim pronađenim problemima

☐

Zatraži evidenciju o servisiranju

Evidencija o servisiranju pokazuje koliko je automobil dobro održavan. Evo što trebaš učiniti dalje:

☐

Zatraži od prodavača knjižicu servisa ili evidenciju održavanja automobila

☐

Provjeri jesu li ulje i filtri redovito mijenjani i kakvo je stanje zupčastog remena

☐

Obrati pažnju na sve servise koje nedostaju ili kasne

☐

Provjeri kilometražu

Provjeri odgovara li kilometražu u ovom izvješću očitavanju brojača kilometara automobila. Tvoja zadnja poznata kilometraža je **149.574 km**. Evo što trebaš učiniti dalje:

☐

Napravi usporedbu očitavanja brojača kilometara i kilometraže navedene u izvješću

☐

Potraži znake lažiranja (istrošene papučice, sumnjivi popravci na kontrolnoj ploči)

☐

Zatraži objašnjenje za sve što izgleda sumnjivo

☐

Obavi pravu probnu vožnju

Pravilna probna vožnja pomoći će ti da uočiš probleme s performansama, upravljanjem ili udobnošću – primijetit ćeš puno više na cesti nego na parkiralištu. Evo što trebaš učiniti dalje:

☐

Vozi se različitim vrstama cesta: autocestama, gradskim prometom i neravnim ili grubim površinama

☐

Osluškuj čudne zvukove ili vibracije

☐

Obrati pažnju na upravljivost i udobnost

☐

Napravi usporedbu sa sličnim automobilima

Provjerom drugih oglasa vidjet ćeš je li tražena cijena poštena ili isplati li se uopće pregovarati. Evo što trebaš učiniti dalje:

☐

Pretraži slične automobile online (ista marka, model, godina, kilometraža)

☐

Usporedi tražene cijene

☐

Provjeri stanje i opremu automobila

☐

Iskoristi ove informacije u pregovorima s prodavačem